Attachment I State Board, Division of Drinking Water - Lead in Schools Testing Program Sweetwater Authority Summary of Lead Testing Results - National School District

School	Sample Site ID	Location Description	Sample Date	Lead Test Results (ppb) ¹	Action Level Exceeded? ² (Yes/No)
Lincoln Acres School	3710025-AAB-A	Kitchen (3 basin sink)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-B	Western end outside restrooms adjacent to Rm. 11 (middle bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-C	Eastern side of bldg. (next to Room 9B; left bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-D	Northern Exterior side of building (outside Room 1B; far right bubbler)	4/12/2017	ND	No
Lincoln Acres School	3710025-AAB-E	Eastern end of bldg. outside of restrooms next to Rm. 21 (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-A	Northern Exterior of Western end outside of Girls restroom (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-B	Southern Exterior by Room 11 (left bubbler)	4/12/2017	5	No
John Otis School	3710025-AAC-C	Northern Exterior on the Eastern end outside of Boys restroom (far right bubbler)	4/12/2017	ND	No
John Otis School	3710025-AAC-D	Kitchen (3 basin sink)	4/12/2017	ND	No
John Otis School	3710025-AAC-E	Northeastern corner of bldg. (lower right bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-A	Exterior of bldg. by room 4 (right bubbler)	4/12/2017	8	No
Kimball School	3710025-AAD-B	Western Exterior of bldg by room 3 (far left bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-C	Southern Exterior next to room 10 by Boys restroom (left bubbler)	4/12/2017	ND	No
Kimball School	3710025-AAD-D	Kitchen (3 basin sink, right faucet)	4/12/2017	ND	No
Kimball School	3710025-AAD-E	Wester Exterior of bldg. (left bubbler)	4/12/2017	ND	No
El Toyon School	3710025-AAE-A	Inside kitchen (3-basin sink)	4/11/2017	ND	No
El Toyon School	3710025-AAE-B	Boys and Girls restroom adjacent to Room 7 (right side bubbler)	4/11/2017	ND	No
El Toyon School	3710025-AAE-C	South side adjacent to Room 17 (far left bubbler)	4/11/2017	ND	No
El Toyon School	3710025-AAE-D	South Exterior between Admin and Lounge (left bubbler)	4/11/2017	6	No
El Toyon School	3710025-AAE-E	South exterior between K3 and K4 (right bubbler)	4/11/2017	ND	No
Ira Harbison School	3710025-AAF-A	Southern Exterior of bldg. (far left bubbler)	4/11/2017	20	Yes
Ira Harbison School	3710025-AAF-A	Southern Exterior of bldg. (far left bubbler)	5/25/2017	ND	No

State Board, Division of Drinking Water - Lead in Schools Testing Program Sweetwater Authority Summary of Lead Testing Results - National School District

School	Sample Site ID	Location Description	Sample Date	Lead Test Results (ppb) ¹	Action Level Exceeded? ² (Yes/No)
Ira Harbison School	3710025-AAF-B	North End of bldg. by Multi-purpose bldg. (far left bubbler)	4/11/2017	7	No
Ira Harbison School	3710025-AAF-C	Kitchen (3 basin sink right faucet)	4/11/2017	ND	No
Ira Harbison School	3710025-AAF-D	Restroom Exterior by Room 7 (left fountain right bubbler)	4/11/2017	10	No
Ira Harbison School	3710025-AAF-E	Upper Playground (far right bubbler)	4/11/2017	6	No
Central School	3710025-AAG-A	Inside kitchen (3-basin sink faucet)	4/11/2017	ND	No
Central School	3710025-AAG-B	East side of bldg. (right bubbler)	4/11/2017	10	No
Central School	3710025-AAG-C	West end of bldg. between Boys and Girls restrooms (right bubbler)	4/11/2017	ND	No
Central School	3710025-AAG-D	East end of bldg. between Boys and Girls restrooms (right bubbler)	4/11/2017	ND	No
Central School	3710025-AAG-E	P3 North fence of play area (outside fence lower bubbler)	4/11/2017	ND	No
Las Palmas School	3710025-AAH-A	Southern side of bldg. by Room 10 (far left bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-B	Southern Exterior corner of bldg. by stage (far right bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-C	Kitchen (3 basin sink right faucet)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-D	Eastern Exterior corner of bldg. (far right bubbler)	4/12/2017	ND	No
Las Palmas School	3710025-AAH-E	West Exterior of bldg. (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-A	Kitchen (3 basin sink right faucet)	4/12/2017	ND	No
Olivewood School	3710025-AAI-B	Northeastern corner of bldg. exterior (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-C	West end of bldg. (far left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-D	Eastern side of bldg. exterior in center (left bubbler)	4/12/2017	ND	No
Olivewood School	3710025-AAI-E	East end of bldg. (far left bubbler)	4/12/2017	ND	No
Palmer Way School	3710025-AAJ-A	Outside of PS-1 in playground area (lowest bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-B	West Exterior of bldg. between Boys and Girls restrooms (far lower left bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-C	Northern Exterior of bldg. (far right bubbler)	4/11/2017	ND	No
Palmer Way School	3710025-AAJ-D	Between bldg. rooms B2 and C5 (far right bubbler)	4/11/2017	5	No
Palmer Way School	3710025-AAJ-E	Kitchen (3-basin sink right faucet)	4/11/2017	ND	No
Rancho de la Nacion Schoo	3710025-ABA-A	Outside of Boys and Girls restroom (right side of bubbler)	4/11/2017	ND	No
Rancho de la Nacion Schoo	3710025-ABA-B	Outside of Boys and Girls restroom (left bubbler)	4/11/2017	5	No
Rancho de la Nacion Schoo	3710025-ABA-C	Northern side of bldg. (left side bubbler)	4/11/2017	ND	No
Rancho de la Nacion Schoo	3710025-ABA-D	Kitchen (3-basin sink)	4/11/2017	ND	No
Rancho de la Nacion Schoo	3710025-ABA-E	Inside classroom 11	4/11/2017	ND	No

¹ND = Not Detected

²The California Action Level for lead is 15 ppb; no corrective actions are required for lead test results ≤ 15 ppb.